

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401850965

Date Received:
11/27/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 95960

Name of Operator: WEXPRO COMPANY

Address: P O BOX 45003

City: SALT LAKE CITY State: UT Zip: 84145-0601

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

April Stegall

307-352-7561

april.stegall@dominionenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692400195

Inspection Date: 09/26/2018

FIR Submit Date: 10/05/2018

FIR Status: _____

Inspected Operator Information:

Company Name: WEXPRO COMPANY

Company Number: 95960

Address: P O BOX 45003

City: SALT LAKE CITY State: UT Zip: 84145-0601

LOCATION - Location ID: 312852

Location Name: STATE OF COLORADO-611N97W Number: 16SENW County: MOFFAT

Qtrqtr: SENW Sec: 16 Twp: 11N Range: 97W Meridian: 6

Latitude: 40.914950 Longitude: -108.299510

FACILITY - API Number: 05-081-00 Facility ID: 222612

Facility Name: STATE OF COLORADO Number: 2

Qtrqtr: SENW Sec: 16 Twp: 11N Range: 97W Meridian: 6

Latitude: 40.914950 Longitude: -108.299510

CORRECTIVE ACTIONS:

1 CA# 119365

Corrective Action:

There are three CAs in this Section.
CA#1) Remove debris from Location.
CA#2) Assess vegetation in Fall 2018; reseeding / inter-seeding/ applying remedies as indicated where desirable vegetation is not Progressing.
CA#3) Control Weeds

Date: 11/30/2018

Response: CA COMPLETED

Date of Completion: 11/27/2018

Please see attachments. Wexpro Company has obtained Disturbance/Reclamation Monitoring results for above listed well pad and will be using the information to determine when/if the well pad will need to be reseeded. Final reclamation dirt work and seeding of the well pad were completed in the fall of 2017, and may not have had

Operator Comment: enough time to establish. Wexpro will continue to monitor the pad yearly until Final Abandonment. The well pad is also on the yearly spray list for bareground and noxious weed treatments.
Debris from location has been removed and disposed of.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attachments. Wexpro Company has obtained Disturbance/Reclamation Monitoring results for above listed well pad and will be using the information to determine when/if the well pad will need to be reseeded. Final reclamation dirt work and seeding of the well pad were completed in the fall of 2017, and may not have had enough time to establish. Wexpro will continue to monitor the pad yearly until Final Abandonment. The well pad is also on the yearly spray list for bareground and noxious weed treatments.
Debris from location has been removed and disposed of.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: April Stegall

Signed: _____

Title: Reclamation Agent

Date: 11/27/2018 9:34:44 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
| 401851009 | Monitoring Data |
| 401851010 | Photo from field |
| 401851011 | Photo from field |
| 401851012 | Photo from field |
| 401851014 | Photo from field |

Total Attach: 5 Files