

Inspection Photos

11/26/2018

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 312233

Inspection Doc. Number: 682504211
Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312233



Photo 1: Photo taken from the well facing north. Photo shows one of the two barrels on location that have not been removed or placed into secondary containment.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312233



Photo 2: Photo taken from the well facing north. Photo barrels on location that have not been removed or placed into secondary containment.



Photo 3: Photo taken from the well location facing northwest. Photo shows northwest anchor is not marked in accordance with 1003.a

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312233



Photo 4: Photo taken from meter shed. Photo shows barrels have been removed.



Photo 5: Photo taken from meter shed. Photo shows additional signage has been placed on tank.