

Inspection Photos
Location Name: BANTA RIDGE UNIT 3
Location ID: 05-103-07513
Inspection: 679701874



Photo 1. Location looking west.



Photo 2. Emergency number not valid.

Inspection Photos
Location Name: BANTA RIDGE UNIT 3
Location ID: 05-103-07513
Inspection: 679701874



Photo 3. Unmarked deadman.



Photo 4. Pit with weeds.