

Inspection Photos

Location Name: BANTA RIDGE FED 14-18-1-103

Location ID: 05-103-10426

Inspection: 679701880



Photo 1. Location looking west.



Photo 2. Buried tank without label.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources