

Inspection Photos

Location Name: BANTA RIDGE FED 10-8-1-103

Location ID: 05-103-10412

Inspection: 679701882



Photo 1. Location looking northwest.



Photo 2. Buried tank without complete labeling.

Inspection Photos

Location Name: BANTA RIDGE FED 10-8-1-103

Location ID: 05-103-10412

Inspection: 679701882



Photo 3. Container without label.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources