

Inspection Photos

Location Name: BANTA RIDGE FED 7-18-1-103

Location ID: 05-103-10386

Inspection: 679701884



Photo 1. Location looking northwest.



Photo 2. Buried tank without labels.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: BANTA RIDGE FED 7-18-1-103

Location ID: 05-103-10386

Inspection: 679701884



Photo 3. Uncapped or locked out tag out risers.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources