

Inspection Photos

Location Name: BANTA RIDGE FED 12-18-1-103

Location ID: 05-103-10249

Inspection: 679701887



Photo 1. Location looking north.



Photo 2. Buried tank without labels.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: BANTA RIDGE FED 12-18-1-103

Location ID: 05-103-10249

Inspection: 679701887



Photo 3. Unmarked deadman.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources