

Inspection Photos

Location Name: WEAVER RIDGE 13-9, 13-9H, 13-16

Location ID: 05-103-10580, 11781, 11782

Inspection: 679701889



Photo 1. Location looking south.



Photo 2. All tanks missing 400 BBL capacity.



Inspection Photos

Location Name: WEAVER RIDGE 13-9, 13-9H, 13-16

Location ID: 05-103-10580, 11781, 11782

Inspection: 679701889



Photo 3. No wellhead sign on 13-9.



Photo 4. Vehicle fire from previous day.



Inspection Photos

Location Name: WEAVER RIDGE 13-9, 13-9H, 13-16

Location ID: 05-103- 05-103-10580, 11781, 11782

Inspection: 679701889



Photo 5. Container without label.



Photo 6. Container without label.



Inspection Photos

Location Name: WEAVER RIDGE 13-9, 13-9H, 13-16

Location ID: 05-103- 05-103-10580, 11781, 11782

Inspection: 679701889



Photo 7. Cellar filled with fluid with 6" of free board.

