

PUCKETT 261-36
API# 05-045-08927
Inspection # 689702112



PUCKETT 261-36
API# 05-045-08927
Inspection # 689702112



Fence around separator is in disrepair.