

Location Name: Carol W. Byrd Trust – Chandler #1 Battery
Inspection Date: 8/27/2018



Photo # - 1



Location Name: Carol W. Byrd Trust – Chandler #1 Battery
Inspection Date: 8/27/2018



Photo # - 2

Tank battery view north from southeast corner



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Carol W. Byrd Trust – Chandler #1 Battery
Inspection Date: 8/27/2018



Photo # - 3

Tank battery view north from southwest corner



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Carol W. Byrd Trust – Chandler #1 Battery
Inspection Date: 8/27/2018



Photo # - 4

Production pit view west from northeast corner, weeds need control and berms eroding into cropland



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Carol W. Byrd Trust – Chandler #1 Battery
Inspection Date: 8/27/2018



Photo # - 5

Production pit view southwest from northeast corner, weeds need control and berms eroding into cropland



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Carol W. Byrd Trust – Chandler #1 Battery
Inspection Date: 8/27/2018



Photo # - 6

Production pit view south from northeast corner, weeds need control and berms eroding into cropland



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Carol W. Byrd Trust – Chandler #1 Battery
Inspection Date: 8/27/2018



Photo # - 7

Treater berm, drums with no secondary containment, unmarked riser outside containment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Carol W. Byrd Trust – Chandler #1 Battery
Inspection Date: 8/27/2018



Photo # - 8

View west from southeast corner of treater berm, weeds need control



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Carol W. Byrd Trust – Chandler #1 Battery
Inspection Date: 8/27/2018



Photo # - 9

View west from southwest corner of treater berm, weeds need control, pit berms eroding into adjacent cropland



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Carol W. Byrd Trust – Chandler #1 Battery
Inspection Date: 8/27/2018



Photo # - 10

View west from north access road, weeds need control, pit berms eroding into adjacent cropland



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources