

Inspection Photos

Location Name: BANTA RIDGE 4-18-1-103, 4A-18-1-103, 6-18-1-103, 5-18-1-103

Location ID: 05-103-10248, 11890, 11891, 11892

Inspection: 679701894



Photo 1. Location looking east.



Photo 2. Buried tank without label.

Inspection Photos

Location Name: BANTA RIDGE 4-18-1-103, 4A-18-1-103, 6-18-1-103, 5-18-1-103

Location ID: 05-103-10248, 11890, 11891, 11892

Inspection: 679701894



Photo 3. Container without label.

