

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/29/2018

Submitted Date:

11/29/2018

Document Number:

692600851

**FIELD INSPECTION FORM**

Loc ID 304628 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 75027  
Name of Operator: ROSEWOOD RESOURCES INC  
Address: 2101 CEDAR SPRINGS RD STE 1500  
City: DALLAS State: TX Zip: 75201

**Findings:**

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Krehmeyer, James	970-630-3880 cell	jkrehmeyer@rosewd.com	<a href="#">Keller Cattle Field Insp</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269510	WELL	PR	04/15/2004	GW	125-08787	SWOPE 2-29	PR

**General Comment:**

[Routine Inspection](#)

Location			
<b>Lease Road:</b>			
Type	Other		
comment:	Access wellhead through farm ground		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Ancillary equipment	# 0		corrective date
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date:
Type: Plunger Lift	# 0		
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date:
<b>Flaring:</b>			
Type	<input style="width: 100%;" type="text"/>		
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 269510 Type: WELL API Number: 125-08787 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Central meter run for \(Swope 1-29, 2-29, 3-29\) 1850' NNW of wellhead on south side of CR 26](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT