

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/29/2018

Submitted Date:

11/29/2018

Document Number:

692600852

FIELD INSPECTION FORM

Loc ID 337895 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 75027
Name of Operator: ROSEWOOD RESOURCES INC
Address: 2101 CEDAR SPRINGS RD STE 1500
City: DALLAS State: TX Zip: 75201

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------------------|-----------------------|--|
| Krehmeyer, James | 970-630-3880 cell | jkrehmeyer@rosewd.com | Keller Cattle Field Insp |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 289428 | WELL | PR | 04/08/2007 | GW | 125-10729 | SWOPE 11-28 | PR |

General Comment:

[Routine Inspection](#)

| Location | | | |
|--|---|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Gravel road between circles | | |
| Corrective Action: | | Date: | |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | Lease sign by meter shed | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by wellhead | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Metal panels around wellhead | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Ancillary equipment | # 0 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Meter run is 2465' NE of wellhead | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |
| Comment: | Vertical gas separator 50% buried by meter shed | | |
| Corrective Action: | | Date: | |
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 289428 Type: WELL API Number: 125-10729 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Meter run is 2465' NE of wellhead on south side of CR 26](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other | Pass | Gravel | Pass | | | |

Comment: [Location is farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT