

Inspection Photos

Location Name: CC 0616-21-32 Pad & Pond G Pit

Location ID: #324288 Pit Facility ID: #414402

Inspection Date: November 28, 2018



Photo #1 – Pit sign and leak detection system located on north side of pit.



Photo #2 – Tank battery located NE of pit. Note that tanks lack content/volume labels and NFPA placards.



Inspection Photos

Location Name: CC 0616-21-32 Pad & Pond G Pit

Location ID: #324288 Pit Facility ID: #414402

Inspection Date: November 28, 2018



Photo #3 – Unused equipment west of tank battery (1).



Photo #4 - Unused equipment west of tank battery (2).



Inspection Photos

Location Name: CC 0616-21-32 Pad & Pond G Pit

Location ID: #324288 Pit Facility ID: #414402

Inspection Date: November 28, 2018



Photo #5 – View of Pond G (Facility ID #414402) from NE corner.



Photo #6 – Liner patch on east side of pit dated 11/12/2018.



Inspection Photos

Location Name: CC 0616-21-32 Pad & Pond G Pit

Location ID: #324288 Pit Facility ID: #414402

Inspection Date: November 28, 2018



**Photo #7 – Liner patch on west side of pit dated 11/12/2018.
Note: this photo corresponds to Photo #14 from 11/1/2018
Field Inspection Report.**



**Photo #8 – Holes at NW corner of pit fence have been
repaired (1).**



Inspection Photos

Location Name: CC 0616-21-32 Pad & Pond G Pit

Location ID: #324288 Pit Facility ID: #414402

Inspection Date: November 28, 2018



Photo #9 - Holes at NW corner of pit fence have been repaired (2).



Photo #10 – Position of sandbag beneath inlet hose with hammer union located at NW corner of pit remains unaddressed from previous Field Inspection Report. Compare to Photo #11 from 11/1/2018 Field Inspection Report.

