

Inspection Photos

Location Name: LOWER HORSE DRAW F 2221

Location ID: 05-103-07452

Inspection: 679701912




Photo 1. Well location.



Inspection Photos

Location Name: LOWER HORSE DRAW F 2221

Location ID: 05-103-07452

Inspection: 679701912



Photo 2. Location looking south.



Photo 3. Location looking southeast.



Inspection Photos

Location Name: LOWER HORSE DRAW F 2221

Location ID: 05-103-07452

Inspection: 679701912



Photo 4. Entrance to old least road filled in with wood, rock, and dirt.



Photo 5. Lease road 150 yards into location.

