

Inspection Photos

Location Name: LOWER HORSE DRAW 2231

Location ID: 05-103-09858

Inspection: 679701918



Photo 1. Location looking northeast.



Photo 2. Tank without labels.



Inspection Photos

Location Name: LOWER HORSE DRAW 2231

Location ID: 05-103-0958

Inspection: 679701918



Photo 3. Unused equipment on ground.

