

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401850922
Date Received:
11/27/2018

FIR RESOLUTION FORM

CA Summary:
3 of 4 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Lindsey Rider 970-285-2711 cogcc.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689302297
Inspection Date: 11/06/2018 FIR Submit Date: 11/06/2018 FIR Status:

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335085

Location Name: SHIDELER-66S92W Number: 29SWSE County: GARFIELD
Qtrqr: SWSE Sec: 29 Twp: 6S Range: 92W Meridian: 6
Latitude: 39.492560 Longitude: -107.689860

FACILITY - API Number: 05-045-00 Facility ID: 282861

Facility Name: SHIDELER Number: 29-11C (O29NE)
Qtrqr: SWSE Sec: 29 Twp: 6S Range: 92W Meridian: 6
Latitude: 39.492560 Longitude: -107.689860

CORRECTIVE ACTIIONS:

1 CA# 120242

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Date: 12/06/2018

Response: CA COMPLETED Date of Completion: 11/06/2018

Operator Comment: Valve was replaced.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approval/passing of the FORM 4/FIRR, acknowledges that the Oil and Gas Conservation Commission has received the Notice.
A field inspection will be conducted to evaluate compliance.

2 CA# 120243

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 12/06/2018

Response: CA COMPLETED

Date of Completion: 11/06/2018

Operator Comment: All valves inspected and tightened if needed.

COGCC Decision: Approved

COGCC Representative: Approval/passing of the FORM 4/FIRR, acknowledges that the Oil and Gas Conservation Commission has received the Notice.
A field inspection will be conducted to evaluate compliance.

3 CA# 120244

Corrective Action: Comply with rule 603.f.

Date: 12/06/2018

Response: CA COMPLETED

Date of Completion: 11/20/2018

Operator Comment: Water tank removed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approval/passing of the FORM 4/FIRR, acknowledges that the Oil and Gas Conservation Commission has received the Notice.
A field inspection will be conducted to evaluate compliance.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lindsey Rider

Signed: _____

Title: EHS Lead

Date: 11/27/2018 9:13:16 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401850922	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files