

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/26/2018

Submitted Date:

11/27/2018

Document Number:

688303002**FIELD INSPECTION FORM**
 Loc ID 457667 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 35080Name of Operator: GRAND MESA OPERATING COAddress: 1700 N. WATERFRONT PKWY BL 600City: WICHITA State: KS Zip: 67206**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Brewer, Phyllis	(316) 265-3000	pbrewer@gmocks.com	Designated Agent
Reilly, Michael	(316) 265-3000	mreilly@gmocks.com	Principal Agent
Reilly, Michael	(316) 265-3000	mreilly@gmocks.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457668	WELL	XX	09/27/2018		121-11080	MCLINTOCK 1-9	DG

General Comment:Surface Cementing Inspection

Inspected FacilitiesFacility ID: 457668 Type: WELL API Number: 121-11080 Status: XX Insp. Status: DG**Well Drilling**

Rig: Rig Name: WW Drilling Rig 20 Pusher/Rig Manager: Paco/John
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: YES Unlined Pit: YES Closed Loop: NO Semi-Closed Loop: NO
 Multi-Well: NO Disposal Location: cuttings in pit/fluid in Buzzs Boat IJ

Comment: Surface TD 439'

Corrective Action: _____ Date: _____

Cement**Cement Contractor**

Contractor Name: Hurricane Contractor Phone: _____

Surface Casing

Cement Volume (sx): 300 Circulate to Surface: YES
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____
 Good Return During Job: _____ Cement Type: _____

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND

Comment: Dryland planted in winter wheat, Gordon Creek ~800' east of well, Ogallala water well in Sec 16 (water at 130')**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____ Pass _____

Comment Corrective Action Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____ Pass _____

Comment Corrective Action Date _____

1002c. PROTECTION OF SOILS _____ Pass _____

Comment Corrective Action Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Pass _____

Comment Corrective Action Date _____

1003a. Waste and Debris removed? _____

Comment Corrective Action Date _____

Unused or unneeded equipment onsite? _____

Comment Corrective Action Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment Corrective Action Date _____

Guy line anchors marked? _____

Comment Corrective Action Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Slope Roughening	Pass					
Ditches	Pass					
Berms	Pass			Covering Materials	Pass	

Comment: A Horizon is stockpiled

Corrective Action: _____

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Water FreshLined: YES

Pit ID: _____

Lat: 39.624702Long: -103.328229Reference Point: SE

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Fencing:

Fencing Type: _____

Fencing Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Anchor Trench Present: _____

Oil Accumulation: _____

2+ feet Freeboard: _____

Comment: _____

Corrective Action: _____

Date: _____

Type: Drilling PitLined: NO

Pit ID: _____

Lat: 39.624513Long: -103.326819Reference Point: SE

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Fencing:

Fencing Type: _____

Fencing Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Netting:	
Netting Type:	Netting Condition:
Comment:	
Corrective Action	
Date:	
Anchor Trench Present:	Oil Accumulation: <u>NO</u> 2+ feet Freeboard: <u>YES</u>
Comment:	
Corrective Action	
Date:	