

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2018

Submitted Date:

11/30/2018

Document Number:

679701950**FIELD INSPECTION FORM**
 Loc ID 316123 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 56680Name of Operator: MERRION OIL & GAS CORPAddress: 610 REILLY AVENUECity: FARMINGTON State: NM Zip: 87401**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|----------------|----------------------------|---------|
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us | |
| Waldron, Emily | | emily.waldron@state.co.us | |
| Thompson, Philana | (505) 324-5300 | pthompson@merrion.bz | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 232180 | WELL | PR | 05/01/2018 | GW | 103-09851 | BAXTER PASS 43-21 | PR |

General Comment:

routine well inspection

LocationOverall Good: ☒

| | | | |
|----------------------|--|--|------------------|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sign or label not posted or information inaccurate on tanks or containers 2 containers without labels. Small green tank without NFPA label, contents, and capacity. | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | | Date: 01/31/2019 |
| Type | BATTERY | | |
| Comment: | Sign not posted or information inaccurate at well(s) or battery Missing nearest public road on sign. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | | Date: 01/31/2019 |

Emergency Contact Number:

Comment: 505-324-5300

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|--|-------|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------------------------|---|--|------------------|
| Equipment: | | | corrective date |
| Type: Other | # 0 | | |
| Comment: | Wellhead bull plug leaking gas along threads of small plug on top of bull plug. | | |
| Corrective Action: | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. | | Date: 12/31/2018 |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |

| | | | |
|---------------------------|--------------|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |
| Comment: | 2 containers | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | <50 BBLs | FIBERGLASS AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | 39.694910,-108.955350 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------|----|--|--|
| Yes/No | NO | | |
|--------|----|--|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 232180 | Type: | WELL | API Number: | 103-09851 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing well | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 679701951 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4661594 |