

**Inspection Photo
GGU Daley 1
API # 045-06868
Inspection # 689302469**



Location Photo #1



Location Photo #2, Unmarked deadman.

**Inspection Photo
GGU Daley 1
API # 045-06868
Inspection # 689302469**



Location Photo #3, Missing tank label/information.



Location Photo #4, Missing tank label/information

Inspection Photo
GGU Daley 1
API # 045-06868
Inspection # 689302469



**Location Photo #5, Missing tank
label/information**