

Inspection Photos
Operator: Lorentz Oil & Gas
Lease: Lippoldt 1-23
API #05-009-06554



1. Lease sign



2. Workover rig, Lone Star Rig 1

Inspection Photos
Operator: Lorentz Oil & Gas
Lease: Lippoldt 1-23
API #05-009-06554



3. Rods stacked on ground



4. Tubing stacked on ground

Inspection Photos
Operator: Lorentz Oil & Gas
Lease: Lippoldt 1-23
API #05-009-06554



5. Bottom joints



6. Wellhead dug out