

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2018

Submitted Date:

12/04/2018

Document Number:

679300029**FIELD INSPECTION FORM**
 Loc ID 422486 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		NBL_DJBU_Inspections@NB LENERGY.COM	
Evans, Jacob		jacob.evans@nblenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422486	LOCATION	AC	04/06/2011		-	WILLMANN PC G16-27D TANK	EI

**General Comment:**

This is an environmental inspection in response to spill Document #401854259 reported by Operator. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection. Site has been backfilled, no oily waste stockpiled on location.

Photos attached to document site condition at the time of inspection.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Comment	No indication of any E&P waste remaining on location.			
Corrective Action				Date:

**Spill/Remediation:**

Comment:	Excavation appears complete.			
Corrective Action:	The Operator shall submit a Form 27 Site Investigation and Remediation Workplan for the investigation and remediation of impacts to groundwater in accordance with Rule 909.c. The Form 27 Workplan may be submitted with the excavation and site assessment results, but should be submitted no later than 90 days from the Spill Report Date in order to resolve this release.			Date: 02/26/2019

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679300030	Site Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4664216">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4664216</a>