

## Inspection Photos

Location Name: GENTRY 15-29-4-103

Location ID: 05-103-08580

Inspection: 679701974



**Photo 1. Location looking south**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: GENTRY 15-29-4-103

Location ID: 05-103-08580

Inspection: 679701974



**Photo 2. Tank without label.**



**Photo 3. Tank without label.**

