

Inspection Photos

API#077-08135

Operator: Caerus

Inspection Number: 692400425

Inspection Date: 11/21/2018





Photo#1:
Overview of Location from entry to Southeast.

November 21, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Finch API#077-08135




Photo#2:
Overview of Location from South end of site to North.

November 21, 2018




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Finch API#077-08135



Photo#3:
Areas that appear to have been hydro-mulched and seeded

November 21, 2018



Photo#4:
Areas that appear to have been hydro-mulched and seeded



Photo#5:
View of cut slope area of concern on Southwest side of Location

November 21, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Finch API#077-08135



Photo#6:
View along cut slope.

November 21, 2018



Photo#7:
View of cut slope.



Photo#8:
Access road; subject of variance request.

November 21, 2018



Photo#9:
Access road; subject of variance request.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Finch API#077-08135