

Inspection Photos

Location Name: BICKLING-66N65W /3SESE

Location #: 330208



Photo #1

Bickling 3-44 (05-123-18623) wellsite

Temporarily Abandoned | TA'd



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: BICKLING-66N65W /3SESE
Location #: 330208



Photo #2

Bickling 3-41, 3-42, 3-43, 3-44, Bickling Farms 3-45
Battery - Tanks
Shut-Down



Photo #3

Bickling 3-41, 3-42, 3-43, 3-44, Bickling Farms 3-45
Battery - Separator
Shut-Down