

Inspection Photos

API#077-08100

Operator: Black Hills

Inspection Number: 692400432

Inspection Date: 11/21/2018





Photo#1:
Overview of Location from access road entry to North.

November 21, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Davis API#077-08100



Photo#2:
Overview of Location to East.

November 21, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Davis API#077-08100



Photo#3:
Debris on site.



Photo#4:
Debris on site.

November 21, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Davis API#077-08100



Photo#5:
What appears to be Well head on site.

November 21, 2018



Photo#6:
What appears to be Well head on site.





Photo#7:
Close up of ground conditions at site.



Photo#8:
Close up of ground conditions at site.

November 21, 2018



Photo#9:
Un-reclaimed Access Road.

November 21, 2018



Photo#10:
Un-reclaimed Access Road.