

Inspection Photos

API#077-08404

Operator: Black Hills

Inspection Number: 692400434

Inspection Date: 11/28/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from access road entry to Northeast.

November 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Meador API#077-08404



Photo#2:
Overview of Location to Southwest.

November 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Meador API#077-08404



Photo#3:
Debris on site.



Photo#4:
Debris on site.

November 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Meador API#077-08404



Photo#5:

Area to Southwest of Well, appears, & according to Surface owner has had Pipeline facilities removed.

November 28, 2018



Photo#6:

Area to Southwest of Well, appears, & according to Surface owner has had Pipeline facilities removed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Meador API#077-08404



Photo#7:
Excavated area that may be remnant of Pit.

November 28, 2018



Photo#8:
Excavated area that may be remnant of Pit.



Photo#9:
Un-reclaimed Access Road.

November 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Meador API#077-08404