

Inspection Photos

API#077-08427

Operator: Black Hills

Inspection Number: 692400436

Inspection Date: 11/28/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location to Southwest from road entry (some evidence of vehicle traffic into Location).

November 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Horseshoe Canyon API#077-08427



Photo#2:
View of Location to Northwest. Insert, close up of weedy area.

November 28, 2018



Photo#3:
Natural Drainage from off site is depositing sediment onto site.

November 28, 2018



Photo#4:
Natural Drainage from off site is depositing sediment onto site.



Photo#5:
Chanel erosion developing in areas

November 28, 2018



Photo#6:
Chanel erosion developing in areas.



Photo#7:
Area where Stormwater flow may be inhibiting
vegetation establishment.

November 28, 2018



Photo#8:
Area where Stormwater flow maybe inhibiting
vegetation establishment.



Photo#9:
Close up of ground conditions & vegetation in
area of concern.

November 28, 2018



Photo#10:
Close up of ground conditions & vegetation in
area of concern.



Photo#11:
Undercutting of rocked drain and wattles.

November 28, 2018



Photo#12:
Undercutting of rocked drain and wattles.