

Inspection Photos

Operator: BP Production

API: 05-067-06951

Date: 11/9/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing within the interim reclamation areas and largely comprised of grasses and shrubs such as smooth brome (*Bromus inermis*), sand dropseed (*Sporobolus cryptandrus*) and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of musk thistles (*Carduus nutans*) within the western edge of the working area. Approximately 100 individuals observed.