

Inspection Photo (s)
Juhan Astral Federal 1-26
API # 05-045-05084
Inspection # 689302563



Location Photo #1



Location Photo #2

Inspection Photo (s)
Juhan Astral Federal 1-26
API # 05-045-05084
Inspection # 689302563



Location Photo #3, Unmarked deadman.



Location Photo #4, Battery sign inaccurate.

Inspection Photo (s)
Juhan Astral Federal 1-26
API # 05-045-05084
Inspection # 689302563



Location Photo #5, Tank Missing capacity information.