

Inspection Photo (s)
Rulison Federal 35-94
API # 05-045-06012
Inspection # 689302579



Location Photo #1



Location Photo #2, Inaccurate battery sign.

Inspection Photo (s)
Rulison Federal 35-94
API # 05-045-06012
Inspection # 689302579



Location Photo #3, Weeds/Debris across location.



Location Photo #4, Weeds/Debris across location.

Inspection Photo (s)
Rulison Federal 35-94
API # 05-045-06012
Inspection # 689302579



Location Photo #5, Weeds/Debris across location.

Location Photo #6, Weeds/Debris across location.

Inspection Photo (s)
Rulison Federal 35-94
API # 05-045-06012
Inspection # 689302579



Location Photo #7, Weeds/Debris across location.