

Inspection Photos

12/10/2018

Operator: RINCON OPERATING CO - 74660

Location ID: 395295

Inspection Doc. Number: 682504258

Morgan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the south end of the location, facing northwest. Photo shows overview of the location. Photo also shows vegetation on the location has not achieved a uniform establishment, and that vegetation has failed to establish on the cut slopes.



Photo 2: Photo taken from the south end of the location, facing northwest. See comments under photo 1.



Photo 3: Photo taken from the southwest end of the pad, facing west. Photo shows vegetation has failed to achieve a uniform establishment, and stormwater runoff has caused erosion degradation on the pad.



Photo 4: Photo taken from the southwest end of the pad, facing north. Photo shows vegetation has failed to achieve a uniform establishment, and stormwater runoff has caused erosion degradation on the pad.



Photo 5: Photo taken from the west end of the pad, facing west. Photo shows vegetation has failed to achieve a uniform establishment, and stormwater runoff has caused erosion degradation on the pad.



Photo 6: Photo taken from the northwest end of the pad, facing southwest. Photo shows vegetation has failed to achieve a uniform establishment, and stormwater runoff has caused erosion degradation on the pad.



Photo 7: Photo taken from the south end of the pad. Photo shows vegetation has not achieved a uniform establishment in accordance with 1004.a



Photo 8: Photo taken from the north end of the pad. Photo shows vegetation has not achieved a uniform establishment in accordance with 1004.a



Photo 9: Photo taken from the adjacent reference area. Photo shows reference vegetation for compare/contrast to vegetation on pad.