

Inspection Photos
Location Name: Cuykendall-Lauck#2
Location ID:317921



Photo 1 WH

Photo 2 PU

Inspection Photos
Location Name: Cuykendall-Lauck#2
Location ID:317921



Colorado Oil and Gas Conservation Commission
40.13933, -104.48151, 1475.0m
Dec 11, 2018 10:57:35



Colorado Oil and Gas Conservation Commission
40.13934, -104.48152, 1475.4m
Dec 11, 2018 10:58:16

Photo 3 TNK BTRY

Photo 4 Stained soil under VLV in back of Production tanks

Inspection Photos
Location Name: Cuykendall-Lauck#2
Location ID:317921



Photo 5 Production H2O tank

Photo 6 Sep house