

Stormwater Inspection

December 4, 2018

Operator: 8 NORTH LLC - 10575

Location ID: 321397

Inspection Document #: 674902300

Boulder County, CO

SENE Section 12 T1S R69W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: 8 NORTH LLC /1S69W12
Location ID: 321397



Photo 1. Photo taken from the facility location along the access road, facing North. Appears stormwater runoff is causing rill erosion along the access road between the facility and the drainage to the North.



Photo 2. Photo taken along the access road, facing North. See comments from Photo 1.

Inspection Photos
Location Name: 8 NORTH LLC /1S69W12
Location ID: 321397



Photo 3. Photo taken along the access road, facing North. See comments from Photo 1.



Photo 4. Photo taken along the access road, facing South. See comments from Photo 1.

Inspection Photos
Location Name: 8 NORTH LLC /1S69W12
Location ID: 321397



Photo 5. Photo taken along the access road, facing South. See comments from Photo 1.



Photo 6. Photo taken along the access road, facing South. See comments from Photo 1.

Inspection Photos
Location Name: 8 NORTH LLC /1S69W12
Location ID: 321397



Photo 7. Photo taken along the access road near the drainage, facing North. See comments from Photo 1.



Photo 8. Photo taken within the drainage adjacent to the access road showing the sediment deposit within the drainage, facing Southwest.

Inspection Photos
Location Name: 8 NORTH LLC /1S69W12
Location ID: 321397



Photo 9. Photo taken within the drainage adjacent to the access road, facing Southwest. See comments from Photo 8.



Photo 10. Photo taken within the drainage adjacent to the access road, facing Southwest. See comments from Photo 8.