

Inspection Photos
Location Name: Richardson G #1
API: 05-067-07752



BMPs along cut back on western edge of location.



Absorbent wipes and stained gravel near base of well head.

Inspection Photos
Location Name: Richardson G #1
API: 05-067-07752



Stained gravel and absorbent wipes near well head.



Well is tagged out for Spill/Release Point ID #459307.