

**Inspection Photo (s)**  
**Gypsum Ranch B3**  
**API # 05-045-16013**  
**Inspection # 6893026011**



**Location Photo #1**



**Location Photo #2**



**Inspection Photo (s)**  
**Gypsum Ranch B3**  
**API # 05-045-16013**  
**Inspection # 689302611**



**Location Photo #3, Unmarked deadman.**



**Location Photo #4, Debris on location.**