

Inspection Photos
Operator: Springdale Partners LLC
Lease: Springdale Unit Baney State 16-11
API #05-075-09256



1. Lease sign, Incorrect emergency contact number



2. Wellhead equipment, Junk, weeds

Inspection Photos
Operator: Springdale Partners LLC
Lease: Springdale Unit Baney State 16-11
API #05-075-09256



3. Engine shed, weeds



4. Unused equipment, weeds