

Inspection Photos

12/12/2018

Operator: FRITZLER RESOURCES INC - 31257

Location ID: 316949

Inspection Doc. Number: 682504275

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the southwest end of the location, facing north. Photos 1-3 provide an overview of the location and interim areas from north, northeast to east.

Inspection Photos
Operator: FRITZLER RESOURCES INC - 31257
Location ID: 316949



Photo 2: See comment under photo 1.



Photo 3: See comment under photo 1.



12.12.2018

Photo 4: Photo taken from the southeast corner of the location facing north. Photo shows various unused equipment being stored on the interim areas. This is equipment not needed for production and needs to be removed and properly stored.



Photo 5: Photo taken from the north end of the pump unite, facing southwest. Photo shows various unused equipment being stored on the interim areas. This is equipment not needed for production and needs to be removed and properly stored.



Photo 6: Photo taken from the north end of the pump unit, facing north. Photo shows a barrel being stored on the location without secondary containment. This is improper materials management.

Inspection Photos
Operator: FRITZLER RESOURCES INC - 31257
Location ID: 316949




Photo 7: Photo of barrel label



Photo 8: Photo taken from the north end of the pump unite, facing north. Photo shows various unused equipment being stored on the interim areas. This is equipment not needed for production and needs to be removed and properly stored.