

Location Name: Fritzler Resources, Inc. – Jolly Oil Skim Pit – Rem #9401  
Inspection Date: 12/11/2018



Photo # - 1

View east at open former oil skim pit excavation



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Fritzler Resources, Inc. – Jolly Oil Skim Pit – Rem #9401  
Inspection Date: 12/11/2018



Photo # - 2

View north at open former oil skim pit excavation



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: Fritzler Resources, Inc. – Jolly Oil Skim Pit – Rem #9401  
Inspection Date: 12/11/2018



Photo # - 3

View west at open former oil skim pit excavation



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Fritzler Resources, Inc. – Jolly Oil Skim Pit – Rem #9401  
Inspection Date: 12/11/2018



Photo # - 4

View south at open former oil skim pit excavation



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources