

Final Reclamation and Stormwater Inspection

December 4, 2018

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 321357

Inspection Document #: 674902295

Boulder County, CO

SENW Section 13 T1S R69W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC – 10459/1S69W13

Location ID: 321357



Photo 1. Photo taken from the access road entrance , facing East. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows and straw crimped mulch and new perennial vegetation.



Photo 2. Photo taken along the access road, facing East. See comments from Photo 1.

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC – 10459/1S69W13

Location ID: 321357



Photo 3. Photo taken along the access road, facing North. See comments from Photo 1.



Photo 4. Photo taken along the access road looking towards the location, facing East. See comments from Photo 1.

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC – 10459/1S69W13

Location ID: 321357



Photo 5. Photo taken from the north end of the location. A List B Colorado Noxious weed species, Scotch thistle (*Onopordum acanthium*), is found on site.



Photo 6. Photo taken from the Southeast end of the facility. Debris removal needed.

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC – 10459/1S69W13

Location ID: 321357



Photo 7. Photo taken from the west end of the location. Several barren spots were observed on the well location. See comments under Photo 1.



Photo 8. Photo taken from the west end of the location. Note the debris on location.