

# Inspection Photos

Operator: BP Production

API: 05-067-07850

Date: 11/29/2018



**Photo 1. View of the western project area from the northwestern corner facing southward.**





**Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is largely comprised of grasses such smooth brome (*Bromus inermis*), western wheatgrass (*Pascopyrum smithii*), and sand dropseed (*Sporobolus cryptandrus*).**





**Photo 3. View of the eastern project area from the southeastern corner edge facing northward.**