

Inspection Photos

Location Name: FORK UNIT 11-7-2-1

Location ID: 05-103-08151

Inspection: 679702216



Photo 1. Location looking northwest.



Photo 1. Tank without NFPA label.

