

Inspection Photo (s)
GGU Jolley 13D
API # 05-045-16357
Inspection # 6893026053



Location Photo #1

Location Photo #2

Inspection Photo (s)
GGU Jolley 13D
API # 05-045-16357
Inspection # 6893026053



Location Photo #3, Stained soil next to the heater treater.



Location Photo #4, Debris on location.

**Inspection Photo (s)
GGU Jolley 13D
API # 05-045-16357
Inspection # 6893026053**



Location Photo #5, Unmarked deadman.