

**Inspection Photo (s)**  
**Federal 32D**  
**API # 05-045-19680**  
**Inspection # 6893026059**



**Location Photo #1**



**Location Photo #2**



**Inspection Photo (s)**  
**Federal 32D**  
**API # 05-045-19680**  
**Inspection # 6893026059**



**Location Photo #3, Stained soil at separator,  
near scrubber pot.**



**Location Photo #4, Stained soil at separator,  
near scrubber pot.**