

Inspection Photo (s)
Jolley KP 334-8
API # 05-045-20987
Inspection # 689302664



Location Photo #1



Location Photo #2

Inspection Photo (s)
Jolley KP 334-8
API # 05-045-20987
Inspection # 689302664



Location Photo #3



Location Photo #4, Unmarked Flow line Riser.

Inspection Photo (s)
Jolley KP 334-8
API # 05-045-20987
Inspection # 689302664



Location Photo #5, Unused equipment in tank battery.



Location Photo #6, Missing tank capacity on all tanks.