

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/17/2018

Submitted Date:

12/17/2018

Document Number:

675001525**FIELD INSPECTION FORM**

Loc ID 334443 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|---------------------------------------|---------------------------------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | All Inspections |
| Clark, Chris | 970-263-3607 | cogccnotifications@laramie-energy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 285899 | WELL | PR | 06/29/2007 | GW | 077-09117 | VEGA UNIT 34-431 | PR |
| 286493 | WELL | PR | 08/24/2007 | GW | 077-09134 | VEGA UNIT 34-421 | PR |
| 286494 | WELL | PR | 05/03/2008 | GW | 077-09133 | VEGA UNIT 34-321 | PR |
| 286495 | WELL | PR | 07/08/2007 | GW | 077-09132 | VEGA UNIT 34-414 | PR |
| 286496 | WELL | PR | 08/09/2007 | GW | 077-09131 | VEGA UNIT 34-411 | PR |
| 286497 | WELL | PR | 04/16/2008 | GW | 077-09130 | VEGA UNIT 34-311 | PR |
| 286498 | WELL | PR | 08/24/2007 | GW | 077-09129 | VEGA UNIT 34-314 | PR |
| 286499 | WELL | PR | 09/28/2009 | GW | 077-09128 | VEGA UNIT 34-324 | PR |
| 286528 | WELL | PR | 07/05/2007 | GW | 077-09135 | VEGA UNIT 34-424 | PR |
| 286529 | WELL | PR | 01/09/2008 | GW | 077-09136 | VEGA UNIT 34-331 | PR |
| 293460 | WELL | PR | 11/14/2007 | GW | 077-09452 | VEGA FEDERAL 34-224 | PR |

General Comment:

[This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.](#)

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 911 / Posted Emergency Contact Number 1-800-891-6191

Corrective Action:

Date:

Good Housekeeping:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Horizontal Heated Separator | # 11 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 11 | | |
| Comment: | | | |

| | | | |
|-----------------------|-----|-------|--|
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 9 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| METHANOL | 1 | <50 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 2 | 400 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------------------|---------|--------|
| CONDENSATE | 2 | 400 BBLS | HEATED STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 285899 | Type: | WELL | API Number: | 077-09117 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Wells producing. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286493 | Type: | WELL | API Number: | 077-09134 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Wells producing. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286494 | Type: | WELL | API Number: | 077-09133 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Wells producing. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286495 | Type: | WELL | API Number: | 077-09132 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Wells producing. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286496 | Type: | WELL | API Number: | 077-09131 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Wells producing. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286497 | Type: | WELL | API Number: | 077-09130 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Wells producing. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286498 | Type: | WELL | API Number: | 077-09129 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Wells producing. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286499 | Type: | WELL | API Number: | 077-09128 | Status: | PR | Insp. Status: | PR |

| <u>Producing Well</u> | | | |
|---|------------------|-------|--|
| Comment: | Wells producing. | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>286528</u> Type: <u>WELL</u> API Number: <u>077-09135</u> Status: <u>PR</u> Insp. Status: <u>PR</u> | | | |
| <u>Producing Well</u> | | | |
| Comment: | Wells producing. | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>286529</u> Type: <u>WELL</u> API Number: <u>077-09136</u> Status: <u>PR</u> Insp. Status: <u>PR</u> | | | |
| <u>Producing Well</u> | | | |
| Comment: | Wells producing. | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>293460</u> Type: <u>WELL</u> API Number: <u>077-09452</u> Status: <u>PR</u> Insp. Status: <u>PR</u> | | | |
| <u>Producing Well</u> | | | |
| Comment: | Wells producing. | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | | | | |
| | | Berms | | | | |
| Gravel | | | | | | |
| | | Compaction | | | | |
| | | Ditches | | | | |
| | | Culverts | | | | |
| Compaction | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 675001529 | Inspection 675001525 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4679961 |