

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2018

Submitted Date:

12/10/2018

Document Number:

675001457**FIELD INSPECTION FORM**

Loc ID 334463	Inspector Name: Wentzel, Dougo	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10433</u> Name of Operator: <u>LARAMIE ENERGY LLC</u> Address: <u>1401 SEVENTEENTH STREET #1400</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: <u>18</u> Number of Comments <u>1</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Clark, Chris		cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295035	WELL	PR	04/24/2013	GW	077-09550	NVEGA 23-324	PR
295036	WELL	PR	03/19/2008	GW	077-09551	NVEGA 23-234	PR
295037	WELL	PR	03/01/2011	GW	077-09552	NVEGA 23-231	PR
295750	WELL	PR	04/29/2008	GW	077-09637	NVEGA 23-144	PR
295751	WELL	PR	04/29/2008	GW	077-09636	NVEGA 26-211	PR
295752	WELL	PR	07/19/2008	GW	077-09635	NVEGA 26-111	PR
295753	WELL	PR	04/29/2008	GW	077-09634	NVEGA 26-311	PR
295754	WELL	PR	04/29/2008	GW	077-09633	NVEGA 23-141	PR
295755	WELL	PR	04/29/2008	GW	077-09632	NVEGA 23-241	PR
295756	WELL	PR	07/23/2013	GW	077-09631	NVEGA 23-341	PR
295757	WELL	PR	04/29/2008	GW	077-09630	NVEGA 23-244	PR
295758	WELL	PR	04/29/2008	GW	077-09629	NVEGA 23-344	PR
295759	WELL	PR	04/29/2008	GW	077-09628	NVEGA 23-331	PR
295760	WELL	PR	06/01/2012	GW	077-09627	NVEGA 23-334	PR

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Tank battery sign posted at well head but missing nearest access road		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	02/11/2019

Emergency Contact Number:

Comment: This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

Corrective Action:

Date:

Good Housekeeping:

Type			
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 14		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		

Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	<50 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	8	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	295035	Type:	WELL	API Number:	077-09550	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Wells producing.								
Corrective Action:						Date:			
Facility ID:	295036	Type:	WELL	API Number:	077-09551	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Wells producing.								
Corrective Action:						Date:			
Facility ID:	295037	Type:	WELL	API Number:	077-09552	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Wells producing.								
Corrective Action:						Date:			
Facility ID:	295750	Type:	WELL	API Number:	077-09637	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Wells producing.								
Corrective Action:						Date:			
Facility ID:	295751	Type:	WELL	API Number:	077-09636	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Wells producing.								
Corrective Action:						Date:			
Facility ID:	295752	Type:	WELL	API Number:	077-09635	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Wells producing.								
Corrective Action:						Date:			
Facility ID:	295753	Type:	WELL	API Number:	077-09634	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Wells producing.								
Corrective Action:						Date:			
Facility ID:	295754	Type:	WELL	API Number:	077-09633	Status:	PR	Insp. Status:	PR

<u>Producing Well</u>			
Comment:	Wells producing.		
Corrective Action:		Date:	
Facility ID: 295755 Type: WELL API Number: 077-09632 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Wells producing.		
Corrective Action:		Date:	
Facility ID: 295756 Type: WELL API Number: 077-09631 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Wells producing.		
Corrective Action:		Date:	
Facility ID: 295757 Type: WELL API Number: 077-09630 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Wells producing.		
Corrective Action:		Date:	
Facility ID: 295758 Type: WELL API Number: 077-09629 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Wells producing.		
Corrective Action:		Date:	
Facility ID: 295759 Type: WELL API Number: 077-09628 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Wells producing.		
Corrective Action:		Date:	
Facility ID: 295760 Type: WELL API Number: 077-09627 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Wells producing.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Compaction				
Compaction						
		Gravel				
Gravel						
Ditches						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401868964	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4671065
675001458	Inspection 675001457 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4671061