

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/12/2018

Submitted Date:

12/12/2018

Document Number:

689702203**FIELD INSPECTION FORM**
 Loc ID 335598 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:23 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284957	WELL	PR	06/05/2006	GW	045-12325	N PARACHUTE MF10C N04 696	PR
284958	WELL	PR	02/01/2014	GW	045-12324	N PARACHUTE MF11D N04 696	PR
284959	WELL	PR	06/05/2006	GW	045-12323	N PARACHUTE WF17A N04 696	PR
284960	WELL	PR	06/05/2006	GW	045-12322	N PARACHUTE MF16C N04 696	PR
284961	WELL	PR	01/08/2007	GW	045-12321	N PARACHUTE MF09C N04 696	PR
284962	WELL	PR	06/05/2006	GW	045-12320	N PARACHUTE MF16A N04 696	PR
284963	WELL	PR	01/01/2010	GW	045-12319	N. PARACHUTE MF12D N04 696	PR
284964	WELL	PR	06/05/2006	GW	045-12318	N PARACHUTE MF09A N04 696	PR
284965	WELL	PR	01/01/2010	GW	045-12317	N.PARACHUTE MF 18C N04 696	PR
284966	WELL	PR	06/05/2006	GW	045-12316	N PARACHUTE MF15C N04 696	PR
284967	WELL	PR	06/05/2006	GW	045-12315	N PARACHUTE MF17C N04 696	PR
284968	WELL	PR	06/05/2006	GW	045-12314	N PARACHUTE MF18A N04 696	PR
300233	WELL	PR	12/05/2009	GW	045-17863	N. PARACHUTE MF10A-4 N04 696	PR
300234	WELL	PR	01/14/2010	GW	045-17862	N.PARACHUTE MF 18A-4 N04 69	PR

300235	WELL	PR	12/30/2009	GW	045-17861	N.PARACHUTE MF10C-4 M04 696	PR
300236	WELL	SI	08/01/2018	GW	045-17860	N. PARACHUTE MF11A-4 N04 696	SI
300237	WELL	PR	02/10/2011	GW	045-17859	N.PARACHUTE MF06D-4 N04 696	PR
301809	WELL	PR	12/30/2009	GW	045-18279	N. PARACHUTE MF15B-4 N04 696	PR
301810	WELL	PR	12/30/2009	GW	045-18280	N. PARACHUTE MF07B-4 N04 696	PR

General Comment:

[Routine FIU General Field Inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign is placed on lease road on the edge of the UNOCAL 24-4D location. Sign is obstructed by brush grown up in front of the sign.		
Corrective Action:	Install sign to comply with Rule 210	Date:	02/13/2019
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 800-791-7691

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 19		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 19		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical containers		
Corrective Action:		Date:	
Type: Gas Meter Run	# 19		

Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	284957	Type:	WELL	API Number:	045-12325	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284958	Type:	WELL	API Number:	045-12324	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284959	Type:	WELL	API Number:	045-12323	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284960	Type:	WELL	API Number:	045-12322	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284961	Type:	WELL	API Number:	045-12321	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284962	Type:	WELL	API Number:	045-12320	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284963	Type:	WELL	API Number:	045-12319	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284964	Type:	WELL	API Number:	045-12318	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID: 284965	Type: WELL	API Number: 045-12317	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 284966	Type: WELL	API Number: 045-12316	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 284967	Type: WELL	API Number: 045-12315	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 284968	Type: WELL	API Number: 045-12314	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300233	Type: WELL	API Number: 045-17863	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300234	Type: WELL	API Number: 045-17862	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300235	Type: WELL	API Number: 045-17861	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300236	Type: WELL	API Number: 045-17860	Status: SI	Insp. Status: SI
---------------------	------------	-----------------------	------------	------------------

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: PRODUCTION RECORDS

Comment:

Corrective Action:

Date:

Facility ID: 300237 Type: WELL API Number: 045-17859 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 301809 Type: WELL API Number: 045-18279 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 301810 Type: WELL API Number: 045-18280 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
				Material Handling And Spill Prevention	Pass	
Berms	Pass					
		Ditches	Pass			
Ditches	Pass					
		Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401872700	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4674364
689702204	Inspection 689702203 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4674359