

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/12/2018

Submitted Date:

12/12/2018

Document Number:

689702208**FIELD INSPECTION FORM**Loc ID 335823 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|-------|-------------------------------------------|---------------------------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| , Caerus Piceance | | COGCC.inspections@caerus oilandgas.com | Piceance inspections only |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 272407 | WELL | PR | 07/14/2005 | GW | 045-10082 | UNOCAL 22-4 | PR |
| 272412 | WELL | PR | 07/24/2005 | GW | 045-10077 | UNOCAL 4-13DX | PR |
| 272416 | WELL | PR | 10/14/2005 | GW | 045-10084 | UNOCAL 33-4D | PR |
| 272417 | WELL | PR | 09/07/2005 | GW | 045-10083 | UNOCAL 23-4D | PR |

General Comment:

Routine FIU General Field Inspection

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|-----------------------------------------------|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Battery sign is obstructed by grown up brush. | | |
| Corrective Action: | Install sign to comply with Rule 210 | Date: | 02/13/2019 |

Emergency Contact Number:

Comment: 800-791-7691

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 272407 | Type: | WELL | API Number: | 045-10082 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 272412 | Type: | WELL | API Number: | 045-10077 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 272416 | Type: | WELL | API Number: | 045-10084 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 272417 | Type: | WELL | API Number: | 045-10083 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|----------------------------------------|--------------------------|---------|
| | | Compaction | Pass | | | |
| Ditches | Pass | | | | | |
| | | | | Material Handling And Spill Prevention | Pass | |
| | | Gravel | Pass | | | |
| Compaction | Pass | | | | | |
| Berms | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 401872703 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4674367 |
| 689702209 | Inspection 689702208 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4674362 |