

Final Reclamation and Stormwater Inspection

December 12, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 317968

Inspection Document #: 674902327

Weld County, CO

SWSW Section 19 T1N R66W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP – 47120/1N66W19

Location ID: 317968



Photo 1. Photo taken towards the location, facing West. Appears the Operator has removed all well equipment from the two P&A wells.



Photo 2. Photo taken from the well location, facing Northwest. See comments form Photo 1.